



SPEEDCLEAN®

FLOWJET™ TROUBLESHOOTING GUIDE



PROBLEM	PROBABLE CAUSE	REMEDY
Inconsistent and/or erratic pressure	<ul style="list-style-type: none">• Nozzle clogged• Inadequate water supply	<ul style="list-style-type: none">• Clean nozzle orifice• 2.2 GPM minimum
Motor stops abruptly	<ul style="list-style-type: none">• Motor thermal breaker tripped	<ul style="list-style-type: none">• Turn off, let unit cool
Motor buzzes but fails to start	<ul style="list-style-type: none">• Inadequate power supply	<ul style="list-style-type: none">• Check for 115VAC/15 A min
Pump runs but produces no flow	<ul style="list-style-type: none">• Pump is not primed	<ul style="list-style-type: none">• Flood suction then restart pump
Unit does not spray chemical	<ul style="list-style-type: none">• Wrong nozzle attached• Pickup hose not in chemical	<ul style="list-style-type: none">• Attach black soap nozzle (size 2540)• Put hose to bottom of chemical